

SECRET

(When Filled In)

FILE INFO

3372

REPRODUCTION PROHIBITED

ACTION	1	DM	6	11	16	
	2		7	12	17	
	3	1	8	13	18	
25X1A	4		9	14	19	
	5		10	15	20	

NNNN SECRET 125452 ZOU 71 CITE

25X1A

IDEAL 1ST/DM-3

SUBJ: PRE-CONDITIONING CART

V2 Df

DSTY:

25X1A

FROM:

25X1A 1. DURING RECEIPT [REDACTED] VISIT TO 133 SRW/OL F/D A STANDARD
PROBLEM TO THAT INDICATED IN PARA TWO OF REF. MESSAGE WAS ENCOUNTERED
IN THE INITIAL CART TO VEHICLE HOOK UP USING THE BLANKET. ONCE THE
BLANKET HAD BEEN PLACED ON THE VEHICLE IT WAS IMMEDIATELY SECURED
IN PLACE USING THE ATTACHED STRAPS. WHEN DIFFICULTY WAS EXPERIENCED IN
CONNECTING CART AIR IN AND OUT HOSES THE BLANKET SECURITY STRAPS WERE
UNFASTENED, ALLOWING THE BLANKET TO HANG FREELY. THROUGH REPOSITIONING
THE THE BLANKET AROUND AIR IN AND AIR OUT CONNECTOR PORTS BOTH HOSE
CONNECTIONS WERE ACCOMPLISHED WITHOUT ENCOUNTERING FURTHER DIFFICULTY.
THIS PROCEDURE HAS BEEN USED ONCE SINCE ON A CREW TRAINING EXERCISE
WITHOUT DIFFICULTY BEING EXPERIENCED IN CART HOSE CONNECTIONS.

25X1A 2. [REDACTED] TRUSTS THAT ABOVE INFO MAY BE HELPFUL.

SECRET